

**SPECIFICATIONS FOR
INSTRUCTIONS FOR PREVENTION OF
MOSQUITO BREEDING**

The following instructions are published by the Construction Industry Development Authority (CIDA) with their letter number 4/1/1/001A dated 2019-10-15 (to be followed by Construction Contractors to Prevent Mosquito Breeding Areas in Sites) which shall be used in respect of this contract.

Table of content

Description	Page no.
Instructions; English version	6bs-1 to 6bs-3
Instructions; Sinhala version	6bs-4 to 6bs-6

Instructions to be followed by Construction Contractors to prevent mosquito breeding areas in Sites.

1. All contractors are responsible to inform Construction Industry Development Authority (CIDA) & Medical Officer of Health (MOH) of the area on Commencement of the Construction Site within one week.
2. The Contractor will be the Key responsible person for maintaining mosquito breeding free environment in the construction site. The contractor shall assign an officer and a subordinate team responsible for keeping the site free of mosquito breeding habitats among the staff of the site. The names of the officer and the team should be displayed at the site.
3. Contractor should ensure that the members of the inspection teams are trained regularly on surveillance and control methods of mosquito breeding. Training of site inspection teams can be requested from the National Dengue Control Unit (NDCU) or Medical Officer of Health (MOH) of the area, through Construction Industry Development Authority (CIDA).
4. Regular site inspections have to be carried out by the team, covering the whole areas (e.g. construction area, storage yard, accommodation areas, cooking/washing area and toilets) for mosquito breeding places according to Form 01. This form should be filled by the assigned officer and should be kept field and a copy to be displayed at the site office for inspection by NDCU, MOH and CIDA.
5. If there are potential/positive mosquito breeding places identified , it is compulsory to adopt quick implementation of source reduction procedures (draining/removing clogged water collection etc.) to eliminate such breeding places immediately. Once detected all such mosquito breeding places, should removed immediately.
6. In situations of water storage and stagnations which cannot be removed by physical means, use of short – term measures such as application of mosquito larvicides becomes essential. The use of larvicides and other temporary mosquito prevention techniques should be adopted in a scientific manner with the technical advice and supervision of MOH of the area.
7. All construction sites must send a monthly summery report on the details of mosquito breeding places and the actions taken for the prevention of mosquito breeding at sites to the MOH of the area and CIDA according to Form 02, based on the information collected from regular site inspections gathered according to Form 01.
8. In the event of any suspected dengue patient reported from a site, assigned officer should inform it immediately to the MOH of the area for necessary control measures to mitigate the spread of the dengue.
9. If any construction site contradicting these instructions to keep the site free of mosquito breeding and endangering the health and safety of all site workers and neighbouring community, CIDA as the authorized regulatory body, follow upon disciplinary procedure imposed on contractors of construction sites to prevent repetition of the same offence.
10. Cooperation of construction contractors is much appreciated for the smooth and effective implementation of instructions given above for the prevention and control of transmission of dengue fever among the community in and around all construction sites.

Monthly report on inspection of dengue breeding places in instruction sites.

General Information

- ◆ Contractor ◆ Site/Project
- ◆ Name of the responsible officer and contact number
- ◆ Client ◆ Month
- ◆ MOH Division

Information about site inspection and dengue cases reported

Availability of a dedicated team for regular inspection of mosquito breeding places	Yes/No
Number of potential breeding places detected during previous month	
Received services by pest control agency during previous month	Yes/No
If yes, Name of the agency No.of times the service provided
MOH health team made inspection visits during the previous month	Yes/No
Any warnings given/Red notice issued	Yes/No
Number of fever patients reported during previous month

Information about the actions taken on detection of breeding places/to prevent breeding places Indicate (Yes/No)

Potential water collected machinery and equipment in the premises and in the vicinity was kept under a shelter	Yes/No
Unused containers were stored under a shelter	
The floors, balconies, flower pots, temporary covers (polythene), concrete roof and canopies were placed without clogging water	
Other fittings including iron/PVC pipes were covered with end caps to prevent water collection.	
Water storage containers/ tanks were covered to prevent mosquito breeding and the water collecting containers were cleaned daily	
Scrub/brushed the inner surface of water collected tanks/containers at least once in three days.	
Drains and gullies were set up to flow	
Collected water in the lift wells were removed every 3 days	
Discarded material, debris and unused goods were discarded properly	
Solid waste was sorted out and properly disposed.	
The reusable or discarded tyres were stored/sand filled/pierced to prevent accumulation of water.	
Larvicides were applied to the mosquito breeding places/containers where water could not be removed	
Technical advice was obtained from the respective Medical Officers of Health	

Signature of the responsible officer

- Please send this report to local government (Municipality/Pradeshia Saba), MOH office of the area and CIDA before 10th of the subsequent month.
- Your assistance as a construction contractor to this National programme on Dengue Prevention, is highly appreciated.

වැඩබිම් (Site) තුළ මදුරුවන් බෝවන ස්ථාන වැළැක්වීම සඳහා ඉදිකිරීම් කොන්ත්‍රාත්කරුවන් විසින් පිළිපැදිය යුතු උපදෙස්.

1. ඉදිකිරීම් වැඩබිම ආරම්භ කිරීම සම්බන්ධයෙන් ඉදිකිරීම් කර්මාන්ත සංවර්ධන අධිකාරියට (CIDA) සහ සෞඛ්‍ය වෛද්‍ය නිලධාරී (MOH) වෙත සතියක් තුළ දැනුම් දීම සියලුම කොන්ත්‍රාත්කරුවන්ගේ වගකීමක් වන්නේය.
2. ඉදිකිරීම් වැඩබිම මදුරුවන් බෝ වීමෙන් තොර පරිසරයක් ලෙස පවත්වා ගැනීමේ ප්‍රදාන වගකිය යුතු පුද්ගලයා වන්නේ කොන්ත්‍රාත්කරුය. වැඩබිම මදුරුවන් බෝවීමෙන් තොර කලාපයක් ලෙස පවත්වාගෙන යාමට එම වැඩබිමෙහි සේවයෙහි නියුතු කාර්යය මණ්ඩලයෙන් නිලධාරියෙකු සහ ඔහු යටතේ සේවක කණ්ඩායමක් කොන්ත්‍රාත්කරු විසින් පත් කල යුතුය. එසේ පත් කරන ලද නිලධාරියාගේ සහ කණ්ඩායමෙහි නම් වැඩබිම තුළ ප්‍රදර්ශණය කළ යුතුය.
3. මදුරුවන් බෝවීම පාලනය සහ පරීක්ෂා කිරීමේ ක්‍රම පිළිබඳව පිරික්සුම් කණ්ඩායමට නිරතුරුව පුහුණුවක් දීමට කොන්ත්‍රාත්කරු සහතික විය යුතුය. එවැනි පුහුණුවක් ජාතික ඩෙංගු මර්ධන ඒකකය (NDCU) හෝ ප්‍රාදේශීය සෞඛ්‍ය වෛද්‍ය නිලධාරී (MOH) වෙතින් (CIDA) හරහා ඉල්ලුම් කල හැක.
4. එම කණ්ඩායම විසින් සියලුම ප්‍රදේශ ආවරණය වන පරිදි වැඩබිම පිරික්සුමට භාජනය කළ යුතුය. (උදා. ඉදිකිරීම් ප්‍රදේශය, ගබඩා අංගනය, නවාතැන් පර්ලු, පිසීම/සේදීම කරනු ලබන ප්‍රදේශ සහ වැසිකිළි පද්ධතිය) මෙය ආකෘති පත්‍ර - 1 ට අනුකූලව සිදුකල යුතුය. මෙම ආකෘති පත්‍රය පත්කල නිලධාරියා සම්පූර්ණ කල යුතු අතර එය ලිපිගොනුවක බහා පිළිවෙලට තැබිය යුතුය. එමෙන්ම එහි පිටපතක් වැඩබිම කාර්යාලයේ NDCU, MOH, සහ CIDA විසින් සිදු කරනු ලබන සෝදිසි කිරීම් සඳහා ප්‍රදර්ශනය කල යුතුය.
5. එවැනි මදුරුවන් බෝවිය හැකි / සාධනීය සලකුණු සහිත ස්ථාන හමුවූ විට එවැනි බෝවන ස්ථාන තුරන් කිරීම සඳහා එම මූලාශ්‍ර අවම කිරීමේ ක්‍රමවේද ඉතා ඉක්මනින් අනුගමනය කල යුතුය. ජලය හිස් කිරීම, ජලය ඇහිරුණු ස්ථාන ඉවත් කිරීම) ආදිය එවැනි මදුරුවන් බෝවිය හැකි ස්ථාන හමුවූ සැනින් එය ඉවත්කිරීම ඉතා ඉක්මනින් සිදුකල යුතුය.
6. ජලය රැඳී ඇති සහ ජලය එකතුවී ඇති ස්ථාන භෞතිකව ඉවත් කිරීමට නොහැකි අවස්ථාවන් වල කීට නාශක ප්‍රතිකර්ම වැනි කෙටි කාලීන පියවර ගැනීම අත්‍යවශ්‍යය. කීට නාශක යෙදීම සහ අනෙකුත් තාවකාලික මදුරු මර්ධන ක්‍රම විද්‍යාත්මක අයුරින් ප්‍රදේශයේ සෞඛ්‍ය වෛද්‍ය නිලධාරී (MOH) ගේ තාක්ෂණික උපදෙස් සහ අධීක්ෂණය යටතේ සිදුකල යුතුය.
7. සියලුම ඉදිකිරීම් වැඩබිම්, ආකෘති පත්‍රය 11 ට අනුකූලව පරිශ්‍රයේ මදුරුවන් බෝවිය හැකි ස්ථාන සහ ඒ සඳහා ගත් මදුරු මර්ධන ක්‍රියාමාර්ග පිළිබඳව මාසික ලුහුඬු වාර්තාවක් ප්‍රදේශයේ MOH, සහ CIDA වෙත යැවිය යුතුය. එම වාර්තාව සඳහා ආකෘති පත්‍රය - 1 ට අදාළව ලබාගත් තොරතුරු භාවිතා කළ හැක.
8. වැඩබිමෙහි ඩෙංගු රෝගියෙකු යැයි සැක සහිත පුද්ගලයෙකු වාර්තා වුවහොත් අදාළ පත්කල නිලධාරියා ප්‍රදේශයේ සෞඛ්‍ය වෛද්‍ය නිලධාරී (MOH) වෙත මේ බව ඉතා ඉක්මනින් දැනුම් දී ඩෙංගු රෝගය ව්‍යාප්ත වීම අවම කිරීමට අවශ්‍ය පාලන පියවර ගැනීම සඳහා ක්‍රියා කළ යුතුය.
9. කිසියම් ඉදිකිරීම් වැඩබිමක් මෙම උපදේශ නොසලකා හරිමින් වැඩබිමෙහි සේවකයන් සහ අසල්වැසි ප්‍රජාවගේ ද සෞඛ්‍යය සහ සුරක්ෂිත භාවය අනතුරේ හෙළමින් ක්‍රියා කළහොත්, බලයලත් නියාමන ආයතනය ලෙස CIDA, ඉදිකිරීම් වැඩබිම් කොන්ත්‍රාත්කරුවන් වෙත, එම වැරද්ද නැවත සිදු කිරීම වැළැක්වීම සඳහා විනයානුකූල ක්‍රියා මාර්ග පැනවිය යුතුය.
10. සියලුම ඉදිකිරීම් වැඩබිම් තුළ හා අවට ප්‍රජාව අතරේ ඩෙංගු රෝගය ව්‍යාප්ත වීම වැළැක්වීම සහ පාලනය සඳහා ඉහත දක්වා ඇති උපදෙස් එලදායි ලෙස ක්‍රියාත්මක කිරීම සඳහා කොන්ත්‍රාත්කරුවන්ගේ සහය ඉතා අගය කොට සලකනු ලැබේ.

සාමාන්‍යය තොරතුරු

කොන්ත්‍රාත්කරු වැඩබිම / ව්‍යාපෘතිය

වගකිව යුතු නිලධාරියාගේ නම සහ දුරකථන අංකය

සේවා දායකයා

සෞ.වෛ.නි. කාර්යාලය මාසය

ස්ථාන පරීක්ෂා කිරීම හා බෙංගු රෝගීන් පිළිබඳ තොරතුරු

මදුරුවන් බෝවිය හැකි ස්ථාන නිතර පරීක්ෂා කිරීම සඳහා කැපවූ කණ්ඩායමක් සිටීම.	ඔව්/නැත
පසුගිය මාසය තුළ හඳුනාගත් මදුරුවන් බෝවිය හැකි ස්ථාන ගණන	
පසුගිය මාසය තුළ ලියාපදිංචි පළිබෝධ පාලන ආයතනයක සේවය ලබාගන්නා ලදී.	ඔව්/නැත
එසේ නම්, එම ආයතනයෙහි නම
සේවාව ලබාදුන් වාර ගණන	
පසුගිය මාසය තුළ සෞ. වෛ.නි. කාර්යාලයේ සෞඛ්‍ය කණ්ඩායම් වැඩබිම පරීක්ෂා කිරීමට පැමිණි වාර ගණන
අනතුරු ඇඟවීම් දීම / රතු නිවේදන නිකුත් කිරීම.	ඔව්/නැත
පසුගිය මාසය තුළ වාර්තා වූ උණ රෝගීන් ගණන

හඳුනා ගත් මදුරුවන් බෝවන ස්ථාන සඳහා ගන්නා පියවර පිළිබඳ තොරතුරු (ඔව්/නැත සඳහන් කරන්න)

පරිශ්‍රය තුළ සහ අවට ඇති ජලය රැස්විය හැකි යන්ත්‍රෝපකරණ හා උපාංග වැසි ජලය රැස් නොවන සේ වහලක් යට ලබන ලදී.	ඔව්/නැත
භාවිතා නොකරන තාවිච්චි හා භාජන ජලය නොරැඳෙන සේ ගබඩා කරන ලදී.	
මහල්, සඳළුතල හා මල් පෝච්චි, තාවකාලික ආවරණ (පොලිතින්, ඉටි කොළ) කොන්ක්‍රීට් වහල (Slab) හා කැනපි මත ජලය නොරැඳෙන සේ සකස් කරන ලදී.	
යකඩ /PVC බට ඇතුළු අනිකුත් සවිකෘත (Fittings) තුළ ජලය නොරැඳෙන සේ ආවරණ (End cap) දමන ලදී.	
ජලය රැස්කර ගන්නා භාජන /වැකි මදුරුවන්ට ඇතුළු විය නොහැකි සේ හොඳින් ආවරණය කිරීම හෝ රැස් කරන ජලය දවසක් හැර දවසක් මාරු කිරීම සිදු කරන ලදී.	
ජලය රැස් කරන වැකි/භාජන යනාදියේ ඇතුළත පෘෂ්ඨ අවම වශයෙන් දින තුනකට වරක් බුරුසු වකින් හොඳින් අතුල්ලා පිරිසිදු කරන ලදී.	
කානු, ගලි වලවල් තුළ ජලය ගලා යන සේ සකස් කරන ලදී.	
සෝපාන ලී තුළ රැඳී ජලය දින 03 කට වරක් ඉවත් කරන ලදී.	
ඉවතලන ද්‍රව්‍ය, සුන්බුන් හා භාණ්ඩ නිසි පරිදි බැහැර කරන ලදී.	
සන අපද්‍රව්‍ය වෙන්කර නිසි ලෙස බැහැර කරන ලදී.	
නැවත භාවිතයට ගන්නා හෝ ඉවතලන ටයර් ජලය එක්රැස් නොවන සේ ගබඩා කරන/වැලි පුරවන/සිදුරු කරන ලදී.	
ඉවත් කිරීමට නොහැකි ජලය රැඳී ඇති ස්ථාන/බඳුන් තුළට කීට නාශක යොදන ලදී.	
අවශ්‍ය තාක්ෂණික උපදෙස් සෞඛ්‍ය වෛද්‍ය නිලධාරී කාර්යාලයෙන් ලබා ගන්නා ලදී.	

.....
වගකිව යුතු නිලධාරියාගේ අත්සන

- මෙම වාර්තාව ප්‍රදේශයේ අදාළ පළාත් ආයතනය, සෞඛ්‍ය වෛද්‍ය නිලධාරී කාර්යාලය හා CIDA වෙත ඊළඟ මාසයේ 10 දිනට පෙර යවන්න .
- ඉදිකිරීම් කොන්ත්‍රාත්කරුවන් වශයෙන් මදුරුවන් බෝවීම වැළැක්වීමේ ජාතික වැඩසටහනට ඔබ දක්වන සහයෝගය ඉතා අගය කොට සලකමු.

